

NAA Safety Alert

Date: May 8, 2018

To: All Staff

Subject: PUI R6-17-001 BOMCO OIL LEAKAGE RETROFIT

From: NAA EHS

A potential safety concern has been identified with PUI R6-17-001 BOMCO Oil Leakage Retrofit. Please **stop all work** related to **PUI R6-17-001** until further notice. The PUI documentation and instructions are being reviewed and updates will be communicated in a timely manner.

In addition, no employee shall use the manual brake release tool referenced in TIP 6.1.14-2 Maintenance Manual for BOMCO 3 Gearless Permanent Magnet Machine for any activity at the moment. This includes any responses to an entrapment.

All other manual brake release tools are to be stored in a locked area and not used unless trained and field verification of use has been conducted per our annual training requirements.

If you have any questions regarding this alert, please contact your Regional Safety Manager or Regional Field Operations Manager.



ALL AFFECTED EMPLOYEES MUST IMMEDIATELY BE NOTIFIED OF THIS SAFETY ALERT