

NAA Safety Alert

Date: 9/6/2021

To: All Field Associates, Supervisors **Subject:** Sharp edge caused cut to hand

From: EH&S Department

Description:

On 9/6/2021 a mechanic was taking a callback on a vendor unit, when he arrived, he found that the doors were recycling on the first floor, he determined that the issue was with the door operator. He accessed the 2nd floor hoistway door and had inserted the door wedge tool and as he rose to his feet, he gripped the sight guard and his gloved hand (approved cut proof A4 glove) slid down the sight guard cutting the glove and right ring finger requiring 4 stitches.

This sight guard had a very sharp serrated edge. This is a reminder to always to check for sharp edges and deburr them with deburring tool MT-105052 and replacement blades MT-105052-1. All mechanics should have this tool on hand. Refer to TIP 41.1-52.







ALWAYS- Wear proper PPE for the task and complete a thorough JHA and Hazscan **NEVER-** Use unapproved PPE.